


- 1. Plug the USB to RS232 converter into the Windows PC.
- 2. Go to Device manager. (located in control panel)
- 3. Under the Other devices drop-down should be "USB.2.0-Ser!"




- 4. Right click on "USB.2.0-Ser!"
- 5. Click on "Update Driver Software..."




6. Click on "Browse my computer for driver software"




7. Click on "Let me pick from a list of device drivers on my computer"




- 8. Click on "Show All Devices"
- 9. Click on "Next"




## 10. Click on "Have Disk..."




- 11. Navigate and select "CH341SER.INF" file provided.
- 12. Click on "Open"




## 13. Click on "OK"



## 14. Click on "Next"



## 15. Click on "Close'



16. If installation was successful "USB-SERIAL CH340" will now be visible under the Port dropdown.

